



Tree condition survey of trees
at
The Fairground, Stratfield Mortimer

Surveyed by
Ben Abbatt

Dip. Arb. (RFS), BA (Hons), MICFor, MRICS, CEnv
Arboricultural Association Registered Consultant

Client
Stratfield Mortimer Parish Council
27 Victoria Road
Mortimer
Reading
RG7 3SH
www.stratfield-mortimer.gov.uk

Report date
5th April 2023

Report reference
J719.05

© Sapling Arboriculture Limited 2023



Institute of
Chartered Foresters



CEnv
Chartered
Environmentalist

Sapling Arboriculture Ltd

Holbache, Mount Pleasant Road, Alton, Hants,
GU34 2RS

T: 01420 550 160

E: enquiries@saplingarboriculture.com

W: www.saplingarboriculture.com

Table of Contents

| | |
|---|----|
| 1. INSTRUCTION | 3 |
| 2. INTRODUCTION | 4 |
| 3. STATUTORY CONTROLS | 5 |
| 4. LIMITATIONS | 6 |
| 5. TREE SURVEY FINDINGS | 7 |
| 6. DISCUSSION | 8 |
| 7. RECOMMENDATIONS | 9 |
| APPENDICES | 10 |
| <i>Appendix 1: tree survey data</i> | 11 |
| <i>Appendix 2: tree survey plan</i> | 28 |
| <i>Appendix 3: general notes</i> | 29 |
| <i>Appendix 4: key to tree survey data</i> | 30 |
| <i>Appendix 5: surveyor qualifications and experience</i> | 31 |

1. Instruction


- 1.1 I was instructed by Bernise O'Reilly, Assistant to the Clerk, Stratfield Mortimer Parish Council, to carry out a tree condition survey of trees at the Fairground, paying particular attention to any features that may pose a significant hazard to persons or property, and to produce a tree survey report including the provision of management recommendations with priorities.
- 1.2 The tree condition assessment is to be carried out in relation to the landowner's duty under the Occupier's Liability Act 1984 and common law. Presumption for tree management will be in favour of retention of the tree(s) where appropriate.
- 1.3 The client has raised concerns relating to the trees including their condition, proximity to the playground, structures, dwellings and highway.

2. Introduction

- 2.1 The Fairground is an area of open space with Windmill Road to the north, Hammonds Heath to the east, The Street to the south and residential housing to the west of King Street. The area is effectively flat. There is a playground and multi use games area in the centre west, tennis courts in the centre, Mortimer Community centre and car parking accessed from the Street in the centre south, Mortimer cricket ground to the southeast, and informal open space to the north. There are a number of public rights of way across the public open space. The pond area to the southeast is registered as common land on the West Berkshire Council online mapping service.
- 2.2 The trees subject to the survey stand principally around the perimeter of the site with a band of young trees in the centre east to west.

3. Statutory controls

- 3.1 The online mapping tool provided by West Berkshire Council, accessed on 5th April 2023 identifies that the site is not subject to Conservation Area controls or Tree Preservation Order; see image SAL1:



SAL1 Data provided by the council website¹.

- 3.2 The Forestry Act 1967 does not apply as the trees grow on public open space (s9(2)(b)²).
- 3.3 As no statutory controls apply, the recommended works can be carried out without reference to the planning authority or forestry authority.
- 3.5 This document does not consider specific covenants.

¹ <https://gis2.westberks.gov.uk/webapps/OnlineMap/?vln=TREE%20PRESERVATION%20ORDERS>

² <https://www.legislation.gov.uk/ukpga/1967/10/section/9>

4. Limitations

- 4.1 The tree survey was carried out from ground level, with the aid of binoculars where appropriate, using the Visual Tree Assessment (VTA) process. The VTA process is used to identify significant tree features that may have significant bearing upon the condition (physiological and structural) and management of the tree.
- 4.2 Typical significant defects that are identified are referred to in Lonsdale, D., "Hazards from Trees, a general guide" (FCPG13) published in 2000 by the Forestry Commission, Lonsdale, D., "Principles of tree hazard assessment and management" published in 1999 and 2001 and reprinted in 2013 by the Forestry Commission, and Mattheck, C., "The body language of trees" published in 1994 by the Department of the Environment and 2015 by Karlsruhe Institute of Technology.
- 4.3 Reasonable access around the base of the trees is required to carry out a tree survey. Where this is not feasible, these parts of the tree may not be fully assessed. If a view of the entire structure of the tree(s) is limited, for instance by the properties in private ownership or obscured by vegetation, this is a limitation to the tree survey and some parts of the tree may not be able to be fully surveyed. In this instance, full access was not available on the west side of the site due to vegetation and the canopy overhanging adjacent properties was not able to be fully viewed, although views from within the site, with the benefit of binoculars, provided a reasonable view of the trees. A number of trees are subject to ivy growth, epicormic growth at the base, and / or vegetation impeding the survey of the tree(s).
- 4.4 Trees are dynamic structures and as such their condition and health may change in a short period of time, particularly in relation to changes in their immediate environment and circumstances, and as such the survey relates only to the visible condition found on the day of the survey. Tree(s) should be re-surveyed on a regular basis so that the change in condition can be identified. An appropriate time period between surveys may be up to 5 years depending upon the species, condition of the trees, their maturity / size and the context within which the tree(s) grow. Recommendations for the period between surveys are given.
- 4.6 No soil investigations have been carried out.

5. Tree survey findings

- 5.1 The survey was carried out on 28th March 2023. I was unaccompanied during the site visit. The weather on the day of the site visit was clear, dry with low wind speeds.
- 5.2 The table of findings of the tree survey can be found in Appendix 1.
- 5.3 I have plotted the approximate new tree positions on the council's Parish Online system to correlate between the tree condition survey (Appendix 1) and the specific trees surveyed on site. Position of the trees plotted is approximate and the specific trees will need to be identified through their approximate position shown on the tree survey plan, condition notes given in the tree survey text and the reference tag number given in the tree survey text.

6. Discussion

- 6.1 The majority of works relates to low branches requiring removal of low canopy branches (crown lifting) to allow the safe passage of pedestrians and vehicles, leaning trees, proximity to buildings, mechanical damage to the base of trees, and ivy and vegetation clearance to allow survey. These types of issues fall within the normal routine annual management.
- 6.2 Some tree works, for instance removal of deadwood, proximity to footpaths, and increased potential for failure and / or harm requires the works to be implemented in a shorter timescale to reduce the potential for harm / damage.
- 6.3 The greater the amount of pruning work carried out, the greater the potential for undesirable physiological and structural impacts upon the retained trees (refer to British Standard 3998:2010 Recommendation for tree works paragraph 7.2.4 extent of pruning works). Therefore, works recommendations given seek to reasonably control the risks identified whilst minimising the potential impact upon retained trees to aid their retention in the landscape for as long as reasonably practicable. Additionally, tree works recommendations are kept to a minimum to minimise the potential aesthetic impacts that can occur through excessive tree works.
- 6.4 To conclude, in my consideration of the site, its location, use, frequency of occupation, the potential hazards that the trees present, the condition of the trees and potential for failure, and the potential size of the failure parts, I have provided tree works recommendations with priorities to aid the retention of the trees in the landscape where feasible and these works are detailed in section 7 and Appendix 1.

7. Recommendations

- 7.1 I have considered the findings of the tree survey within the context of the health and vitality of the trees and the circumstances within which they are located.
- 7.2 Recommended works are detailed in Appendix 1 for each tree with associated priorities. The priorities mean that the recommended works should be carried out within specified timescales detailed in Appendix 3 key to tree survey data.
- 7.3 Works are considered a 'High' priority and should be complete within 1 month from the date of this survey. The priority is considered based on the condition of the tree and its position and context. No trees were identified as being subject to a high priority.
- 7.4 Works are considered a 'Moderate' priority and should be complete within 3 months from the date of this survey. The priority is considered based on the condition of the tree and its position and context. Five trees were identified as being subject to a high priority.
- 7.5 Works are considered a 'Low' priority and should be complete within 12 months from the date of this survey. The priority is considered based on the condition of the tree and its position and context. Fifty-eight trees were identified as being subject to a high priority.
- 7.6 Tree works should be carried out in accordance with British Standard 3998:2010 Recommendations for Tree Works and in particular biosecurity / avoidance of transmission of disease and pathogens (4.3), extent of pruning works (7.2.4), and natural target pruning (7.2.5). A tree contractor ought to carry out works in accordance with this British Standard and be aware of these specific elements.
- 7.7 Tree works, except high priority and felling works, ideally to be carried out in the late summer (September) to aid the trees to respond to the pruning wounds in the most effective manner. The worst time to implement tree works to retained trees is in spring (and secondly around leaf fall) and, therefore, these time periods (spring and leaf fall) ought to be avoided where possible to reduce the physiological impact upon retained trees.
- 7.8 Resurvey of the trees ought to be complete by the 1st September 2026. Resurvey is important as the condition of trees alters over time.

Appendices

Appendix 1: tree survey data

Tree Condition Survey Data

Site Fairground, Stratfield Mortimer
 Date of survey 28th March 2023
 Job reference J719.05
 Surveyor Ben Abbatt
 Resurvey To be complete by the 1st September 2026

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|--------------|-------------|-------------------------|----------------------|---|--|----------|
| T | 501 | Whitebeam | Middle aged | Good | Fair | Slight lean towards car parking area. | No works required at the time of the survey. | ~ |
| T | 502 | Willow | Middle aged | Good | Fair | Historic failed stem over the car parking area. | Crown reduction to a final height of 5m with a 2m horizontal radial branch spread. | Low |
| T | 503 | Hornbeam | Middle aged | Good | Good | Close to adjacent building. | Clear building by 2m retaining overhanging branches outside this distance. | Low |
| T | 504 | Sorbus | Middle aged | Good | Good | Close to adjacent building. | Clear building by 2m retaining overhanging branches outside this distance. | Low |
| T | 505 | Norway Maple | Middle aged | Good | Good | | No works required at the time of the survey. | ~ |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|------------|-------------|-------------------------|----------------------|--|---|----------|
| T | 506 | Cherry | Mature | Fair | Fair | Resin bleeding from the lower stem. Lean of lower stem away from building. Close to adjacent building. | Clear building by 2m retaining overhanging branches outside this distance. | Low |
| T | 507 | Scots Pine | Mature | Good | Good | Low branches. | Crown lift to 3m. Clear fence by 1m. | Low |
| T | 508 | Scots Pine | Middle aged | Fair | Fair | Suppressed by adjacent trees. Ivy impedes survey. | Sever ivy at base and remove to 2m using hand tools only and taking care to avoid damage to the bark beneath. | Low |
| T | 509 | Scots Pine | Mature | Good | Good | Low branches. | Crown lift to 3m. Clear fence by 1m. | Low |
| T | 510 | Ash | Mature | Good | Good | Species susceptible to ash dieback https://www.forestryresearch.gov.uk/tools-and-resources/fthr/pest-and-disease-resources/ash-dieback-hymenoscyphus-fraxineus/ [relates to all ash trees within the survey]. Close to adjacent building. | Clear building by 2m retaining overhanging branches outside this distance. | Low |
| T | 511 | Whitebeam | Middle aged | Good | Good | Close to adjacent building. | Clear building by 2m retaining overhanging branches outside this distance. | Low |
| T | 512 | Lime | Young | Good | Good | 13no. Potential for mower and trimmer damage to base of trees. Low branches. | Formative prune to create single upright leader and form with good branch structure. Crown lift to 2m. Cut and remove turf to 50mm depth within 1m of the tree and replace with wood chip or bark mulch to a settled depth of 75mm within 1m of the tree. Reinstate mulch annually. | Low |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|-------------------|---------|-------------|-------------------------|----------------------|---|---|----------|
| T | 513 | Ash | Mature | Good | Good | Two stems from 2m. Typical moderate (25 to 100mm diameter) deadwood. | Remove deadwood more than 25mm diameter. | Moderate |
| T | 514 | Ash | Mature | Good | Good | Two stems from 2m. Typical moderate (25 to 100mm diameter) deadwood. | Remove deadwood more than 25mm diameter. | Moderate |
| T | 515 | Oak | Mature | Good | Good | c30mm diameter branch caught in the south western canopy adjacent to the footway and carriageway. | Remove branch caught in the canopy. | Low |
| T | 516 | Birch | Mature | Good | Good | 3 stems from 1m with good 'u' shaped tension unions. Mower damage to surface roots. | No works required at the time of the survey. | ~ |
| T | 517 | Maple | Middle aged | Good | Good | Two stems from 1.5m. Ivy obscures survey. | No works required at the time of the survey. | ~ |
| T | 518 | Rowan | Mature | Good | Fair | Twin stems from near the base with tight union. Ivy impedes survey. | Sever ivy at base and remove to 2m using hand tools only and taking care to avoid damage to the bark beneath. | Low |
| T | 519 / 0143 / 0753 | Oak | Mature | Good | Good | Minor deadwood. | No works required at the time of the survey. | ~ |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|---------|-------------|-------------------------|----------------------|---|--|----------|
| T | 520 | | | | | Tree position is between 522 and 523 and therefore data has been moved to between these two recorded data items. See below. | ~ | ~ |
| T | 521 | Oak | Middle aged | Good | Fair | Suppressed by adjacent trees. Previously tip reduced. | No works required at the time of the survey. | ~ |
| T | 522 / 0142 | Oak | Mature | Good | Fair | Rubbing stems. | No works required at the time of the survey. | ~ |
| T | 520 | Oak | Mature | Good | Good | Two stems from 1.1m. Adjacent to the play area. | No works required at the time of the survey. | ~ |
| T | 523 / 139 / 752 | Oak | Mature | Good | Fair | Suppressed by adjacent tree. Adjacent to the play area. | No works required at the time of the survey. | ~ |
| T | 524 / 0138 | Oak | Mature | Good | Good | Ivy and vegetation impedes survey. | Remove deadwood more than 25mm diameter. Sever ivy at base and remove to 2m using hand tools only and taking care to avoid damage to the bark beneath and maintain clear. Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 525 | Oak | Mature | Good | Fair | Intermediate canopy. | No works required at the time of the survey. | ~ |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|-------------------|---------|-------------|-------------------------|----------------------|---|--|----------|
| T | 526 | Oak | Mature | Good | Fair | Intermediate canopy. Vegetation impedes survey. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 527 | Oak | Mature | Good | Fair | Intermediate canopy. Ivy and vegetation impedes survey. | Sever ivy at base and remove to 2m using hand tools only and taking care to avoid damage to the bark beneath. Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 528 | Oak | Mature | Good | Good | Ivy and vegetation impedes survey. | Crown lift to 3.5m. Sever ivy at base and remove to 2m using hand tools only and taking care to avoid damage to the bark beneath and maintain clear. | Moderate |
| T | 529 | Oak | Mature | Good | Fair | Intermediate canopy. Ivy impedes survey. | Crown lift to 3.5m. Sever ivy at base and remove to 2m using hand tools only and taking care to avoid damage to the bark beneath and maintain clear. | Low |
| T | 530 / 0133 / 0745 | Oak | Mature | Fair | Fair | Intermediate canopy. Sparse canopy. Ivy impedes survey. | Crown lift to 3.5m. Sever ivy at base and remove to 2m using hand tools only and taking care to avoid damage to the bark beneath and maintain clear. | Low |
| T | 531 / 0132 / 0744 | Oak | Mature | Good | Fair | Intermediate canopy. Low branches. | Crown lift to 3.5m. | Low |
| | | Ash | Middle aged | Good | Fair | Inaccessible due to vegetation. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|-------------------|---------|-------------|-------------------------|----------------------|--|---|----------|
| T | 532 / 0131 / 0743 | Oak | Middle aged | Good | Fair | Suppressed canopy. | No works required at the time of the survey. | ~ |
| T | 533 / 0130 / 0742 | Oak | Middle aged | Good | Fair | Suppressed canopy. Canopy reduced over adjacent garden. Cavity at base. | No works required at the time of the survey. | ~ |
| T | 534 / 0129 / 0741 | Oak | Mature | Good | Good | Typical occasional moderate deadwood. Two stems from near base. Vegetation impedes survey. | Remove deadwood more than 25mm diameter. Clear vegetation within 1.5m of the base of the tree and maintain clear. | Moderate |
| T | 535 | Stump | | | | Ivy covered. | No works required at the time of the survey. | ~ |
| T | 536 / 0128 / 0740 | Oak | Mature | Good | Good | Burr at base. | No works required at the time of the survey. | ~ |
| T | 537 | Oak | Mature | Dead | | Retained monolith adjacent to footpath and adjacent gardens. | Remove. | Low |
| T | 0126 / 0737 | Oak | Mature | Fair | Fair | Slightly sparse canopy. Access impeded by vegetation. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|---------|-----------|-------------------------|----------------------|---|---|----------|
| T | 538 | Oak | Mature | Good | Fair | Suppressed canopy. Vegetation impedes survey. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 539 / 0124 | Oak | Mature | Good | Fair | Recent crown reduction. Vegetation impedes survey. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 540 | Oak | Mature | Dead | | Retained monolith adjacent to footpath and adjacent gardens. | Remove. | Low |
| T | 541 | Oak | Mature | Good | Fair | Suppressed canopy. Vegetation impedes survey. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 542 | Oak | Mature | Good | Fair | Intermediate canopy. Occasional moderate deadwood. Vegetation impedes survey. | Remove deadwood more than 25mm diameter. Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 543 | Oak | Mature | Fair | Fair | Intermediate canopy. Vegetation impedes survey. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 544 | Oak | Mature | Fair | Fair | Intermediate canopy. Vegetation impedes survey. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|---------|-----------|-------------------------|----------------------|--|--|----------|
| T | 545 | Oak | Mature | Good | Good | Suppressed canopy. Vegetation impedes survey. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 546 | Oak | Mature | Good | Good | Suppressed canopy. Vegetation impedes survey. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 547 / 0116 | Oak | Mature | Fair | Fair | Recent crown reduction and canopy over adjacent garden to the west cut back to near the boundary of the site. Two stems from near the base. Vegetation impedes survey. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 548 / 0115 | Oak | Mature | Good | Fair | Recent crown reduction and canopy over adjacent garden to the west cut back to near the boundary of the site. Vegetation impedes survey. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 549 0114 / 0725 | Oak | Mature | Good | Good | Recent crown reduction and canopy over adjacent garden to the west cut back to near the boundary of the site. | No works required at the time of the survey. | ~ |
| T | 550 | Oak | Mature | Good | Good | Recent crown reduction and canopy over adjacent garden to the west cut back to near the boundary of the site. | No works required at the time of the survey. | ~ |
| T | 551 | Oak | Mature | Good | Fair | Suppressed canopy. Excessive lean over the footway. Vegetation impedes survey. | Crown reduction to a horizontal radial branch length of 7m. Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|----------|-------------|-------------------------|----------------------|---|--|----------|
| T | 552 / 0722 | Oak | Mature | Good | Fair | Intermediate canopy. Previously topped with mature regrowth. Vegetation impedes survey. | Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |
| T | 553 | Oak | Mature | Poor | Poor | Removed. | No works required at the time of the survey. | ~ |
| T | 554 | Sycamore | Young | Good | Poor | Poor growing position adjacent to a garage. Multiple stems from the base. | Remove. Treat stump to prevent regrowth. | Low |
| T | 555 | Oak | Middle aged | Good | Good | ~ | No works required at the time of the survey. | ~ |
| T | 556 | Oak | Middle aged | Good | Good | Low branches over the carriageway. | Crown lift to 5m over the carriageway. | Low |
| T | 557 | Oak | Middle aged | Good | Good | Low branches over the carriageway. | Crown lift to 5m over the carriageway. | Low |
| T | 558 | Oak | Mature | Good | Good | Occasional moderate deadwood. Previously topped with mature regrowth. Low branches over the carriageway. Vegetation impedes survey. | Remove deadwood more than 25mm diameter. Crown lift to 5m over the carriageway. Clear vegetation within 1.5m of the base of the tree and maintain clear. | Low |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|----------------|-------------|-------------------------|----------------------|---|--|----------|
| G | 1 | Poplar | Middle aged | Good | Good | Species susceptibility to sucker growth; evident on site. Group is within 10m of the northern boundary and runs adjacent to the boundary. | Remove and treat stump to prevent regrowth. Reason: to prevent the encroachment on the public open space by the sucker growth. | Low |
| T | 559 | Oak | Mature | Good | Fair | Cavity on top side of branch growing towards the public open space. | No works required at the time of the survey. | ~ |
| T | 560 | Oak | Mature | Good | Good | ~ | No works required at the time of the survey. | ~ |
| T | 561 | Oak | Mature | Good | Good | ~ | No works required at the time of the survey. | ~ |
| G | 562 | Willow | Mature | Good | Fair | Coppiced. | No works required at the time of the survey. | ~ |
| G | 2 | Oak and Willow | Middle aged | Good | Fair | Willow susceptible to structural failure. G2 is immediately to the south of the vehicle entrance on the east side of the site and G562. | Coppice willow. Crown lift oak to 5m over carriageway and 2m height over the remainder. | Low |
| T | 563 | Oak | Mature | Good | Good | Typical occasional moderate deadwood. | Remove deadwood more than 25mm diameter. | Low |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|---------|-------------|-------------------------|----------------------|---|--|----------|
| T | 564 | Oak | Mature | Good | Good | Typical occasional moderate deadwood. | Remove deadwood more than 25mm diameter. | Low |
| T | 565 | Oak | Mature | Good | Good | Typical occasional moderate deadwood. | Remove deadwood more than 25mm diameter. | Low |
| T | 566 | Oak | Mature | Fair | Good | Open canopy indicating lower than normal vitality. Typical occasional moderate deadwood. | Remove deadwood more than 25mm diameter. | Low |
| T | 567 | Oak | Mature | Fair | Poor | Recent crown reduction. Series of branch failures and large branch removals. Potential for coalesced decay. | No works required at the time of the survey. | ~ |
| T | 568 | Oak | Middle aged | Poor | Poor | Declining canopy on west side. Remaining part leans towards the carriageway. | Remove. | Low |
| T | 569 | Ash | Mature | Good | Fair | Two competing stems from 3m. Species susceptibility to ash dieback. | No works required at the time of the survey. | ~ |
| T | 570 | Birch | Middle aged | Good | Fair | Broken and hanging branch over the footway. Lean towards footway. | Remove. | Moderate |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|---------|-------------|-------------------------|----------------------|---|---|----------|
| T | 571 | Lime | Mature | Good | Fair | Two competing stems from 3m. Mower damage to structural roots. | Infill topsoil at base to prevent continuing damage to roots. | Low |
| T | 572 | Willow | Mature | Good | Poor | Old coppice adjacent to pond. Species susceptibility to structural failure. | Coppice. | Low |
| T | 573 | Ash | Mature | Good | Fair | Two competing stems from 1.5m. Species susceptibility to ash dieback. | No works required at the time of the survey. | ~ |
| T | 574 | Willow | Mature | Good | Poor | Previously topped. Pholiota squarrosa at base.. | Coppice. | Low |
| T | 575 | Ash | Middle aged | Good | Good | On edge of pond. | No works required at the time of the survey. | ~ |
| T | 576 | Willow | Mature | Good | Poor | Coppiced. On edge of pond. Species susceptibility to structural failure. | No works required at the time of the survey. | ~ |
| T | 577 | Oak | Middle aged | Good | Poor | Suppressed canopy. Lean towards footway. | Remove. | Low |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|--------------|-------------|-------------------------|----------------------|---|--|----------|
| T | 578 | Field Maple | Middle aged | Good | Poor | Poor form. | No works required at the time of the survey. | ~ |
| T | 579 | Willow | Middle aged | Good | Good | Species susceptibility to structural failure. | No works required at the time of the survey. | ~ |
| T | 580 | Norway Maple | Middle aged | Good | Good | ~ | No works required at the time of the survey. | ~ |
| T | 581 | Whitebeam | Middle aged | Good | Good | ~ | No works required at the time of the survey. | ~ |
| T | 582 | Siberian Elm | Mature | Good | Fair | Species susceptibility to structural failure. Recent crown reduction with moderate regrowth. Mower damage to surface roots. | Infill topsoil adjacent to surfaceroots to reduce the potential for future mower damage. | Low |
| T | 583 | Oak | Mature | Good | Good | ~ | Move bench to outside canopy spread to reduce the potential for harm. | Low |
| T | 584 | Oak | Middle aged | Good | Good | ~ | No works required at the time of the survey. | ~ |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|-------------|-------------|-------------------------|----------------------|--|---|----------|
| T | 585 | Lime | Young | Good | Good | 13no. Potential for mower and trimmer damage to base of trees. Low branches. | Formative prune to create single upright leader and form with good branch structure. Crown lift to 2m. Cut and remove turf to 50mm depth within 1m of the tree and replace with wood chip or bark mulch to a settled depth of 75mm within 1m of the tree. Reinststate mulch annually. | Low |
| T | 586 | Whitebeam | Middle aged | Good | Good | ~ | No works required at the time of the survey. | ~ |
| T | 587 | Field Maple | Middle aged | Good | Good | ~ | No works required at the time of the survey. | ~ |
| T | 588 | Whitebeam | Middle aged | Good | Good | ~ | No works required at the time of the survey. | ~ |
| T | 589 | Willow | Mature | Good | Fair | Recent crown reduction. Ivy impedes survey. | Sever ivy at base and remove to 4m using hand tools only and taking care to avoid damage to the bark beneath and maintain clear. | Low |
| G | 590 | Willow | Mature | Good | Poor | Group of fallen and broaden stems on edge of pond. | Coppice. | Low |
| T | 591 | Willow | Middle aged | | | Removed. | No works required at the time of the survey. | ~ |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|--------------------------------|-------------|-------------------------|----------------------|--|--|----------|
| T | 592 | Ash | Mature | Good | Good | Species susceptibility to ash dieback. | No works required at the time of the survey. | ~ |
| T | 593 | Oak | Middle aged | Good | Good | Adjacent to the pond. | No works required at the time of the survey. | ~ |
| T | 594 | Oak | Middle aged | Good | Fair | Suppressed canopy with lean over the pond. | No works required at the time of the survey. | ~ |
| T | 595 | Horse Chestnut | Mature | Good | Fair | Dark exudate and bark cracks on the lower stem commensurate with Horse Chestnut bleeding canker. | Crown lift to 4m over the car parking area. | Low |
| G | 596 | Oak, birch and occasional lime | Middle aged | Good | Good | Close grown. Understorey of gorse impedes survey. | Thin group by 20% every 5 years to achieve a final spacing of 10m between trees. Trees of poor form, structure or vitality to be removed preferentially. | Low |
| T | 597 | Oak | Mature | Good | Good | ~ | Remove bench to outside the canopy to reduce the potential for harm. Remove holly at base of the tree to allow future surveys. | Low |
| T | 598 | Whitebeam | Mature | Good | Good | ~ | No works required at the time of the survey. | ~ |

| Designation | Reference number | Species | Age class | Physiological condition | Structural condition | Condition notes | Condition related tree works | Priority |
|-------------|------------------|-----------------------------|-------------|-------------------------|----------------------|---|--|----------|
| T | 599 | Hornbeam | Middle aged | Good | Fair | Poor form. | No works required at the time of the survey. | ~ |
| T | 600 | Whitebeam | Middle aged | | | Removed. | No works required at the time of the survey. | ~ |
| G | 3 | Oak, birch, Scots pine, ash | Middle aged | Good | Fair | Close grown. Understorey of gorse impedes survey. G3 is the group of trees that run east to west across the centre of the site. | Thin group by 20% every 5 years to achieve a final spacing of 10m between trees. Trees of poor form, structure or vitality to be removed preferentially. | Low |

Appendix 2: tree survey plan

Refer to Parish Online data held by Stratfield Mortimer Parish Council.

Appendix 3: general notes

The tree survey can only be an assessment of the tree at the time of the survey and the tree(s) should be re-surveyed on a regular basis. An appropriate time period between surveys may be up to 5 years depending upon the condition of the trees, their maturity and the target(s). Recommendations for the period between surveys will be given.

As trees are dynamic structures their condition and health may change in a short period of time, particularly in relation to changes in their immediate environment and circumstances. Therefore, the survey is an assessment of the trees at the time of the survey only. If there is a significant change in the immediate environment and circumstances, then this should be brought to the attention of the arboriculturalist so that they may advise accordingly.

I have not specifically checked with the planning authority whether the site is within a Conservation Area or whether the trees are under Tree Preservation Order (TPO), but I have relied upon their published map information. Prior to any tree works confirmation of whether these legal restrictions apply to the site or trees ought to be sought from the planning authority. If the trees stand within a Conservation Area designated under the Town and Country Planning Act the LPA will normally require 6 weeks notice of intention to carry out any tree works as detailed in the survey. If the trees are under TPO then the planning authority will normally require an application for any tree works. Some tree works are exempt, for instance if the trees are dead or dangerous, and certain works can be carried out without application. It is necessary to give the planning authority at least five days notice prior to carrying out any of these tree works under these exemptions. This survey, with recommendations, can be used to support any such application or notice.

Wildlife issues are of significant concern to the general public. A balance has to be found between the protection of wildlife and the need for safety when managing trees. The Wildlife and Countryside Act (1980) and Countryside Rights of Way Act (2000) give statutory protection to wild birds, bats, mammals, some invertebrates and plants. It is important to ensure that this legislation is properly considered when carrying out any works to trees.

Bird nests were not identified whilst on site. However, any Arborist carrying out the tree works should ensure that there is no disturbance to nesting birds prior to the works being carried out. Further guidance upon the appropriate timing of the works can be sought from DEFRA, if necessary. Where nesting birds are found, further information should be sought from DEFRA 08459 33 55 77 or helpline@defra.gsi.gov.uk. Prior to any works being implemented the tree contractor must identify whether there are any bats or birds using the tree as roost or nest. If such habitation is identified, then the tree contractor must obtain the necessary licence from Natural England (0845 601 4523 www.naturalengland.org.uk) to carry out the works.

A bat survey prior to tree works is not recommended, except where there is a high potential for habitat. During the tree works, the contractor should carry out the tree works with bats as an active consideration and follow the current industry best practice, e.g. Arboricultural Association Guidance Note 1 Bats in the context of tree work operations 2011, BS8596 Micro guide to surveying for bats in trees and woodland <https://shop.bsigroup.com/upload/273444/BSI-Bat-Microguide-UK-EN.pdf> which a competent tree contractor should be familiar with.

Biosecurity measures: To minimise the potential for contamination of the tree from other tree works it is appropriate to sterilise tools to be used before and after the works are implemented. Appropriate disinfectant includes Propellar or Cleankill Sanitizing spray. Loose debris is to be brushed off prior to treating with disinfectant to ensure appropriate application. See [http://www.forestry.gov.uk/pdf/FCMS028-guidance.pdf/\\$file/FCMS028-guidance.pdf](http://www.forestry.gov.uk/pdf/FCMS028-guidance.pdf/$file/FCMS028-guidance.pdf) for further information on Biosecurity and <http://www.forestry.gov.uk/forestry/infd-9fjd2d> for disinfectant information.

Appendix 4: key to tree survey data

| | | |
|--|---|---|
| Desig | Designation (T is Tree, G is Group, H is Hedge, W is woodland, S is Stump) | |
| No | Tree number. | |
| Species | Species of tree. | |
| Height | Height measured in metres. | |
| Canopy spread | Canopy spread in metres is taken at the four cardinal points to derive an accurate representation of the crown. | |
| Height of crown | Height in metres of crown clearance above adjacent ground level. | |
| Age Class | Young | A tree considered to be less than approximately 20 years old. |
| | Middle aged | A tree in approximately the first 1/5th of its normal life span with apical dominance (rapidly growing with a clear main leader) and not yet fully at its environmental potential full height. |
| | Mature | A tree in its 2/5ths to 5/5ths of its normal life span with apical dominance lost and at its environmental potential full height. |
| Condition (Physiological and Structural) | Good | A tree of typical physiological and structural condition that requires only general tree works to facilitate its retention in the landscape. |
| | Fair | A tree of impaired physiological and / or structural condition that may require remedial and general tree works to facilitate its retention in the landscape. |
| | Poor | A tree of significantly impaired physiological and / or structural condition that will require remedial and general tree works to facilitate its retention in the landscape if feasible. |
| Recommendations | As per BS3998: 2010 Recommendations for Tree Works. | |
| Priority | Immediate | Works should be carried out immediately as the probability of harm or damage occurring is likely. |
| | High | These works are important to carry out as soon as reasonably possible and any budget available for tree management should be spent upon these trees before the moderate and low categories. Works in this category usually will relate to abatement of risk for harm and or damage to occur. Ideally works in this category are anticipated to be carried out within 1 month. |
| | Moderate | These works are important to carry out as soon as reasonably possible and any budget available for tree management should be spent upon these trees before the low categories. Works in this category usually will relate to abatement of risk for harm and or damage to occur and for the good arboricultural management of the trees. Ideally works in this category are anticipated to be carried out within 3 months. |
| | Low | Works in this category usually will relate to the good arboricultural management of the trees. Ideally works in this category are anticipated to be carried out within 12 months. |
| Re-survey | This is the time period in which it is recommended that the tree is surveyed again. This is based upon the condition of the tree, its location, previous, current and future management. It is normally expressed at a time period from the date of the report / survey, whichever is the sooner. If no time period is noted then the default period is one year. | |

Appendix 5: surveyor qualifications and experience

Ben Abbatt has been involved in the arboricultural industry since the mid 1990s and has worked in a variety of roles within the industry, starting as a forestry contractor, progressing to the surveying and management of forestry and arboricultural contracts for a national forestry company and running the arboricultural section of a horticultural business overseas. Additionally, Ben has worked in local Government at Borough and County levels, providing planning related advice and managing Tree Preservation Orders and Conservation Areas, as well as managing highways trees and contracts.

Since 2006, Ben has been the Director and Principal Consultant of Sapling Arboriculture Ltd.

Ben is a qualified member of the Institute of Chartered Foresters (ICF), Royal Institute of Chartered Surveyors (RICS), Society for the Environment (SocEnv) and the Arboricultural Association (AA), having been an Arboricultural Association Registered Consultant since 2006. He is also a member of the International Society of Arboriculture and the Royal Forestry Society.

He holds many arboricultural and forestry qualifications including the Professional Diploma in Arboriculture awarded by the Royal Forestry Society, the Technicians' Certificate awarded by the Arboricultural Association and an HNC in Forestry.

Ben is also a freelance trainer for LANTRA, delivering courses in Basic Tree Survey and Inspection and Professional Tree Inspection.



© 2023

This document was written by, belongs to and is copyright to Sapling Arboriculture Limited. No responsibility or liability is accepted by Sapling Arboriculture Limited towards any person other than the clients named in this document in respect of the use of this document or reliance on the information contained within it, except as may be designated by law for any matter outside the scope of this document.