

Maintenance Report

Vita Play Limited

The Fairground Mortimer

Vita Play Limited Woodhams Farm New Barn Springvale Road Kings Worthy Winchester SO23 7LB

Site Information

Name of site. The Fairground Mortimer, Reading RG7 3RD

Date of Maintenance: 28/07/2021 Carried out by: Louie Cross



Benches



• 3 qty Backed benches - All fixings checked

<u>Bins</u>



• 4 qty Bins - checked

<u>Fence</u>



- All fence panels checked bolts tight and present, no loose posts
- There are a few bent bars recommendation cut of existing bars and weld replacement bars



<u>Gates</u>



• Ground around gate has worn, consider reinstating

<u>Signage</u>



• All present and fixings tight

Picnic Tables



• All fixings tight and present

<u>Muga</u>



 All panels checked and loose fixings tightened, there is no Anti Climb Signage present

Junior Swings



- All fixings on the swing frame are present and tight
- There is wear on the swing chains which is close to the 40% and will require replacing with the next 6 months
- There is minimal wear on the shackle and bushes, monitor and consider replacing within the next 12 months
- Surface edges have shrunk and beginning to lift, consider carrying out a full perimeter repair





Senior Swings



- All fixings on the swing frame are present and tight
- Surface is beginning to shrink and lift, monitor and carry out repair when required



Horizontal Ladder



- All fixings on the horizontal Ladder are present and tight
- Surface is beginning to shrink and lift, monitor and carry out repair when required



Elephant Rocker



- All fixings on the spring rocker are present and tight
- Loose handle has been tightened
- Surface is beginning to shrink and lift, monitor and carry out repair when required



Motorcycle Rocker



- All fixings on the spring rocker are present and tight
- The spring bracket has broken and will require replacing within the next 6 months
- Surface is beginning to shrink and lift, monitor and carry out repair when required
- Consider replacing foot rests with new compliant ones





Multi Play Unit



- All fixings on the multi-unit are present and tight
- The missing cap and fixing has been replaced
- Surface edges have shrunk and beginning to lift, consider carrying out a full perimeter repair





Steppingstone's



- The steppingstones are present and show no signs of being loose
- There rubber joint is beginning to open up, monitor and replace within the next 12 months



Rocking Horse



- All fixings are present and tight, all bearings have been greased.
- Paint is wearing consider rubbing down and repainting to prevent corrosion
- Surface is beginning to shrink and lift, monitor and carry out repair when required





Chin Up Bars



- All fixings on the chin up bars are present and tight
- Surface edges have shrunk and beginning to lift, consider carrying out a full perimeter repair



Standing Seesaw



- All fixings on the seesaw are present and tight
- The bearings have been greased
- Surface has started to crack, consider carrying out repairs



<u>Seesaw</u>



- All fixings on the seesaw are present and tight
- The bearings have been greased
- Surface has started to crack, consider carrying out repairs



Roundabout



- All fixings on the Roundabout are present and tight
- The bearings have been greased
- There is movement in the bearing this could indicate worn bearings or spindle
- Surface is beginning to shrink and lift, monitor and carry out repair when required
- Paint has started to wear off consider



Freestanding Slide



• All fixings on the slide are present and tight

Orb Rocker



- All fixings on the orb rocker are present and tight
- The Ground has eroded around the orb rocker consider reinstating or using a harder wearing surface.



Blue Spinning Bowl



- All fixings on the Spinning Bowl are present and tight
- The bearings have been greased

Red Spinning Bowl



- All fixings on the Spinning Bowl are present and tight The bearings have been greased

Spinning Disc 1



- All fixings on the Spinning Disc are present and tight
- The bearings have been greased •

Spinning Disc 2



- All fixings on the Spinning Disc are present and tight
- The bearings have been greased

<u>Supernova</u>



- All fixings on the Supernova are present and tight
- The bearings have been greased
- Rubber Strips have been re installed on the underside of the supernova
- The sunken areas in the grass mats have been removed







Pyramid Net



- All fixings on the net are present and tight
- Damaged grass mat has been replaced



Spica Yellow Top



- All fixings on the Spica are present and tight
- Bearings have been greased

Spica Green Top



- All fixings on the Spica are present and tight
- Rubber Step has been damaged Monitor, replace when required
- Bearings have been greased

Rocking Platform



- All fixings on the Platform are present and tight
- Bearings have been greased

Gyro Spiral



- All fixings on the Gyro Spiral are present and tight
- Bearings have been greased
- Rubber on seat has been damaged consider replacing the damaged seat
- Grass mats have sunken into the ground consider lifting and relaying or using an alternate surface



Rigid Skate Roller



- All fixings are present and tight
- Bearing has been greased

Titan Rotator



- All fixings on the Titan are present and tight
- Damaged grass mat has been replaced/ Repaired
- Bearing has been greased
- Seat sleeve is damaged consider replacing
- Chains and shackles are showing wear monitor and consider replacing within the next 6-12 months



<u>Single Pole</u>



• All fixings are present and tight

Tripod Swing



- All fixings on the Tripod swing are
- present and tight Damaged grass mat has been replaced/ Repaired
- Bearing has been greased Chains and shackles are showing wear monitor and consider replacing within the next 12 months
- There is some minor rust showing consider rubbing down treating







